

SAMPLE INSPECTION REPORT

Foundation Pre-Pour

Pearland, Texas

Pre-Pour Foundation Inspection

Brad Leland | TREC License #5229

281-794-9102 | houstonhomeinspector.net

PROPERTY INSPECTION REPORT

Prepared For: _____
(Name of Client)

Concerning: _____, Pearland, TX
(Address of Inspected Property)

By: Brad Leland, Lic #5229
(Name and License Number of Inspector) (Date)

(Name, License Number and Signature of Sponsoring Inspector, if required)

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.state.tx.us.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is not required to move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector will note which systems and components were Inspected (I), Not Inspected (NI), Not Present (NP), and/or Deficient (D). General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing parts, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported as Deficient may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards, form OP-I.

This property inspection is not an exhaustive inspection of the structure, systems, or components. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain

further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Present at Inspection: ☒ Buyer ☐ Selling Agent ☐ Listing Agent ☐ Occupant
 Building Status: ☒ Vacant ☐ Owner Occupied ☐ Tenant Occupied ☐ Other
 Weather Conditions: ☒ Fair ☐ Cloudy ☐ Rain 63F Outside Temp.
 Utilities On: ☒ Yes ☐ No Water ☐ No Electricity ☐ No Gas
 Special Notes: Pre - Pour Foun Inspection

INACCESSIBLE OR OBSTRUCTED AREAS

☐ Sub Flooring ☐ Attic Space is Limited - Viewed from Accessible Areas
☐ Floors Covered ☒ Plumbing Areas - Only Visible Plumbing Inspected
☒ Walls/Ceilings Covered or Freshly Painted ☐ Siding Over Older Existing Siding
☐ Behind/Under Furniture and/or Stored Items ☐ Crawl Space Is Limited - Viewed From Accessible Areas

☒ Mold/Mildew investigations are NOT included with this report, it is beyond the scope of this inspection at the present time. Any reference of water intrusion, is recommended that a professional investigation be obtained.

**NOTICE: THIS REPORT IS PAID FOR BY AND PREPARED FOR THE CLIENT NAMED ABOVE.
 THIS REPORT IS NOT VALID WITHOUT THE SIGNED SERVICE AGREEMENT AND IS NOT
 TRANSFERABLE.**

The inspection report provided by Brad Leland Home Inspections will contain the good faith opinions of the inspector concerning the observable need, if any, on the day of the inspection, for the repair, replacement, or further evaluation by experts of the items inspected. Unless, specifically stated, this report will not include and should not be read to indicate opinions as to the environmental conditions, presence of toxic or hazardous waste or substances, presence of termite or wood destroying organisms, or compliance with codes, ordinances, statutes or restrictions, or the insurability, efficiency, quality, durability, future life, or future performance of any item inspected.

EXAMPLE

When the inspector inspects the roof of a structure he or she may determine that there are no observable signs of water penetration (leaks) at the time of the inspection and that the roof appears to be functioning as intended. Even if this opinion is expressed, it is possible that the roof has a leak but that the ceilings or walls have been repainted, concealing the evidence. Further, although the roof may be functioning as intended at the time of the inspection, the roof still may need to be replaced in the near future, depending on how long ago it was installed.

IMPORTANT NOTICE

WHENEVER A DEFECT OF ANY KIND IS NOTED IN A SYSTEM OR ASPECT OF THE HOUSE, WE RECOMMEND THAT A QUALIFIED (LICENSED) TECHNICIAN INSPECT AND SERVICE THE ENTIRE SYSTEM. SOMETIMES NOTED DEFECTS ARE SYMPTOMS OF OTHER, SOMETIMES MORE SERIOUS, DEFECTS.

Conditions and Limitations

This inspection report expresses the personal opinion of the inspector and is based on the minimum inspection standards set for by The Texas Real Estate Commission. The purpose of this inspection is to provide an opinion on whether or not the items in this report were functional or are in need of repair or require further evaluation by a qualified or when required licensed person. The scope of this inspection is limited to the present condition of visual items only and does not include the disassembly of any properly or the removal of any object including, but not limited to, furniture, siding, or panels that may be obscuring the inspector's visual observation. This inspection does not cover items or conditions that may be discovered only by invasive methods. This inspection is not intended to be technically exhaustive nor is it intended to reveal all existing or potential defects. Rather, it is intended to reflect a careful but limited visual inspection. The information in this report can reduce, but not eliminate the risks associated with the purchase of this structure. Should you determine you desire a more detailed inspection of any area, you may wish to refer to licensed and/or qualified specialists. Since all elements undergo a constant rate of change and deterioration, no prediction of future conditions can be made. This report is not to be considered a warranty or guarantee of the adequacy, performance or useful life of an item, component or system.

This inspection and report was prepared for your exclusive use. Use of this report by, or liability to third parties, present or future owners and subsequent buyers is specifically excluded. Reliance on this report by third parties, present or future owners and subsequent owners is at their risk. No warranty or guaranty to third parties, present or future owners and subsequent owners is implied nor should be assumed.

Photos if included in this report are not intended to represent all conditions present. They are a representation of the circumstances visible but not limited to the specific photo. There may be other similar repairs needed. Service Warranties are very popular but they may have restrictions under which a claim is covered. Minor deviations from the manufactures installation instructions, which are not normally revealed in a general inspection, may be cause for a denial of claim. Client must not expect these warranty services to cover all of your problems, particularly with aging systems. Pay close attention to the respective warranty documents for coverage limitations. This report was prepared on a computer and infrequently a word or part of a sentence may be accidentally deleted or altered. Should you encounter such a condition, please contact me as soon as possible to make necessary correction and provide you with a corrected page(s). If you do not understand comments or recommendations for corrective action, call me prior to your inspection deadline or before closing the transaction for clarification.

The following are not within the scope of this inspection:

- Past or present violations or codes, ordinances or manufactures installation instructions.
- Geological stability or ground conditions on site.
- Determination of absolute structural integrity.
- Determination that all safety hazards have been identified.
- Possible presence of or danger from any potentially harmful substance, pollutants, contaminants and environmental hazards, including but not limited to radon gas, lead paint, lead in water, asbestos, mercury, urea formaldehyde, electro-magnetic fields, noise, odor, and toxic or flammable chemicals. The inspector is not responsible for the determination of conditions which may provide harborage or sustenance for bacterial, mold and fungi, the presence of dirt, dust and other air-borne particles. The client is urged to contact a competent specialist if identification, information and testing of the above are desired.
- Value of or estimated of repairs on the property. We are not a repair company and are prohibited by a provision of The Texas Real Estate License Act from performing repairs on properties that we inspect. It is recommended that the appropriate qualified and licensed craftsmen be contacted for firm bids to perform desired repairs.
- No determination will be made on the operational capacity, quality, and/or suitability for a particular use of the items inspected.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D


I. STRUCTURAL SYSTEMS
☒
☐
☐
☒
A. Foundations

The overall construction of the forms and placement of the reinforcing steel has been done well.



Tendon reinforcing cables are in contact or too close to plumbing drain pipes on the southeast side perimeter footing in the guest bathroom area and at an interior beam in the utility room/master bathroom area. These drain pipes must have a minimum of 1.5 inches clearance from the post tension cables to avoid possible damage to the drain lines.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I	NI	NP	D



The moisture barrier is torn/incomplete in several areas and should be repaired before the concrete is poured.



Report Identification:

Pearland, TX


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I	NI	NP	D
---	----	----	---



There is loose dirt/mud that needs to be removed in several areas of the perimeter footings to achieve a minimum of 26 inches of depth as is called for before the concrete is poured.



Report Identification:

Pearland, TX


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient


I	NI	NP	D
---	----	----	---



Several of the chair tendon cable spacers are damaged and need to be replaced and some were

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I	NI	NP	D

not placed where needed.



The windstorm tie down straps were not installed at the time of this inspection.



It is recommended that the builder be consulted regarding the above issues for correction prior to the concrete being poured.